

Removal of (doffing) personal protective equipment (PPE)



PPE should be removed in an order that mini the potential for cross contamination.

The order of removal of PPE is as follows:

1

Gloves –

the outsides of the gloves are contaminated



Clean hands with alcohol sanitizer

2

Gown –

the front of the gown and sleeves will be contaminated



3

Eye protection -


the outside will be contaminated



4

Mask -

clean hands with alcohol hand rub. Do not touch the front of the mask as it will be contaminated



5

Wash hands with soap and water

